Subject: RE: Harbor Drive Emergency Repair

Date: Tuesday, May 31, 2016 at 11:59:32 AM Pacific Daylight Time

From: David Anderson

To: Klein, Adrienne@BCDC

Also, the culvert is below the bottom plank.



David R. Anderson, PE | **President/CEO**18 Technology Drive, Suite 208, Irvine CA 92618
714 460 8696 p | 714 943 4068 c | <u>danderson@are-corp.com</u>

CONFIDENTIAL/PRIVILEGED COMMUNICATION: This communication, including any attachment(s) thereto, may contain legally privileged and/or confidential information, intended for a specific individual and purpose, and is protected by law. If you are not the intended recipient of this e-mail (or the person responsible for delivering this document to the intended recipient), you are hereby notified that any disclosure, dissemination, copying, printing, or distribution of this communication, and any attachment thereto, or the taking of any action based on information in this e-mail, is strictly prohibited. Interception of e-mail is a crime under the Electronic Communication Privacy Act, 18 U.S.C. 2510-2521 and 2701-2709. If you have received this transmission in error, please notify the individual sending this message, permanently delete the original transmission and its attachment(s) without reading them, or saving them to disk and destroy any copy and printout thereof. Thank you for your cooperation in this matter.

From: David Anderson

Sent: Tuesday, May 31, 2016 11:59 AM

To: 'Klein, Adrienne@BCDC' <adrienne.klein@bcdc.ca.gov>

Subject: RE: Harbor Drive Emergency Repair

Adrienne,

Have not yet located any other photos. I will contact Jake and see if he can join us and also ask him for the date.

Dave



David R. Anderson, PE | President/CEO

18 Technology Drive, Suite 208, Irvine CA 92618 714 460 8696 p | 714 943 4068 c | danderson@are-corp.com

CONFIDENTIAL/PRIVILEGED COMMUNICATION: This communication, including any attachment(s) thereto, may contain legally privileged and/or confidential information, intended for a specific individual and purpose, and is protected by law. If you are not the intended recipient of this e-mail (or the person responsible for delivering this document to the intended recipient), you are hereby notified that any disclosure, dissemination, copying, printing, or distribution of this communication, and any attachment thereto, or the taking of any action based on information in this e-mail, is strictly prohibited. Interception of e-mail is a crime under the Electronic Communication Privacy Act, 18 U.S.C. 2510-2521 and 2701-2709. If you have received this transmission in error, please notify the individual sending this message, permanently delete the original transmission and its attachment(s) without reading them, or saving them to disk and destroy any copy and printout thereof. Thank you for your cooperation in this matter.

From: Klein, Adrienne@BCDC [mailto:adrienne.klein@bcdc.ca.gov]

Sent: Tuesday, May 31, 2016 11:54 AM

To: David Anderson < <u>DAnderson@are-corp.com</u>>

Cc: ncra.mstogner@sbcglobal.net

Subject: Re: Harbor Drive Emergency Repair

Dear Dave,

Thanks for this photo. Do you have any more photographs of the conditions before the repair and of other tidal phases? Please tell me the date and time the photo was taken so I can discern the tide at the time? Where is the culvert? Maybe Jacob could join us on the call at 3pm today?

Sincerely,

Adrienne

Adrienne Klein Chief of Enforcement SF BCDC 455 Golden Gate Ave., Suite 10600 San Francisco, CA 94102-7019 Direct: (415) 352-3609

Main: (415) 352-3600 http://www.bcdc.ca.gov

Please identify the appropriate BCDC permit and enforcement case file numbers in the subject line of your response.

From: David Anderson < DAnderson@are-corp.com>

Date: Saturday, May 28, 2016 at 4:44 AM


To: Adrienne Klein <a drienne.klein@bcdc.ca.gov>

Cc: "ncra.mstogner@sbcglobal.net" <ncra.mstogner@sbcglobal.net>

Subject: Harbor Drive Emergency Repair

Adrienne,

Below is the photo received from NCRA's Operator and statement received from Jacob Park NWP Company's Manager.



Statement from Jacob Park of NWP Co. (NCRA's Freight Operator responsil The top two timbers were put back into place and the road was raised approximately 5 tons of dirt. We never touched the culvert. If we did road would have eroded away and damned the culvert and no water we culvert.

I will see if anyone has a before photo and send before our Tuesday call. Dave Anderson, NCRA's Engineer



David R. Anderson, PE| **President/CEO**18 Technology Drive, Suite 208, Irvine CA 92618
714 460 8696 p | 714 943 4068 c | danderson@are-corp.com

CONFIDENTIAL/PRIVILEGED COMMUNICATION: This communication, including any attachment(s) thereto, may contain legally privileged and/or confidential information, intended for a specific individual and purpose, and is protected by law. If you are not the intended recipient of this e-mail (or the person responsible for delivering this document to the intended recipient), you are hereby notified that any disclosure, dissemination, copying, printing, or distribution of this communication, and any attachment thereto, or the taking of any action based on information in this e-mail, is strictly prohibited. Interception of e-mail is a crime under the Electronic Communication Privacy Act, 18 U.S.C. 2510-2521 and 2701-2709. If you have received this transmission in error, please notify the individual sending this message, permanently delete the original transmission and its attachment(s) without reading them, or saving them to disk and destroy any copy and printout thereof. Thank you for your cooperation in this matter.